

Red Oak Community School District

2011 North 8th Street Red Oak, Iowa 51566 712.623.6600

www.redoakschooldistrict.com

Special Board of Directors Meeting

Meeting Location: Sue Wagaman Board Room Red Oak CSD Administrative Center The Technology Building, Red Oak High School Campus

June 9, 2017 – 12:00 pm

- Agenda -

- 1.0 Call to Order -
- 2.0 Roll Call -
- 3.0 Approval of the Agenda –
- 4.0 General Business for the Board of Directors
 - 4.1 Old Business none
 - 4.2 New Business-Discussion/Approval of purchase of Compressor Replacement on Roof Top Unit at Washington School Building
- 5.0 Next Regular Board of Directors Meeting:

Monday, June 26, 2017 – 6:00 pm Sue Wagaman Board Room

Red Oak CSD Administrative Center

6.0 Adjournment

DOVEL REFRIGERATION

1600 N BROADWAY RED OAK IOWA 51566

Date

Estimate No.

SUPT OF SCHOOL 2011 n 8th TECH BUILDING RED OAK, IOWA 51566

| Item | Description | Qty | | Rate | Total |
|------|----------------------|-----|-----|-----------|-------------|
| 0 | COMPRESSOR | | | 10,357.38 | 10,357.38 |
| 0 | SOLENOID KIT E19S270 | | | 264.62 | 264.62 |
| 0 | SOLENOID KIT E25S270 | | | 396.03 | 396.03 |
| 0 | DRIER C607S | | | 123.82 | 123.82 |
| 0 | LIFT | | | 500.00 | 500.00 |
| ZACH | WORK DONE ZACH | | 1 | 1,500.00 | 1,500.00 |
| 0 | 2ND MAN | | | 1,000.00 | 1,000.00 |
| 0 | SUCTION VALVE | | | 539,66 | 539.66 |
| | DISCHARGE VALVE | | | 352.69 | 352.69 |
|]0 | CONTACTOR | | • | 125.00 | 125.00 |
| | WASHINGTON SCHOOL | | | | |
| | | | | | |
| | · | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | · | | | | |
| · | | | | • | |
| | | | | | |
| | | | | | |
| | | | Tot | al | \$15,159.20 |



June 1, 2017

Red Oak Schools 2011 North 8th Street Red Oak, IA 51566

Re: Compressor Replacement on RTU at Washington

Ray Martin Company is pleased to provide you with the following quote. Work will include the installation of a new compressor for the roof top unit at Washington

Job Scope

- Schedule project with customer
- Schedule and coordinate crane
- Recover all refrigerant from circuit
- Remove failed compressor
- Install new OEM compressor (NOT a rebuild)
- Install 2 new OEM contactors for compressor
- Install new liquid line drier
- Install new crankcase heater
- Evacuate system.
- Charge system with recovered refrigerant
- Start unit and check operation

The above listed work will be completed for the investment of\$14,740.00 (Fourteen Thousand Seven Hundred Forty Dollars & 00/100)

Above listed project does not include any taxes or freight. Any additional repairs that may be required will be billed accordingly.

Compressor comes with one (1) year parts only warranty. An extened warranty that covers from year two (2) through year five (5) is available for an additional \$2,200.00

| Accepted by | | | | | |
|--|--------|-------------|--|--|--|
| (Print) | | (Signature) | | | |
| PO | Amount | Date | | | |
| If you have any questions, please feel free to contact me. | | | | | |
| Respectfully, | | | | | |
| Joel Nelson 402-553-7300 Ext. 112 402-506-0683 cell | | | | | |

Joel.Nelson@RayMartinCo.com